

BLACK-MAX™

Cathodic Rust Arrestor

Application Tip Sheet

Do not sandblast or grind rust away because **BLACK-MAX™** must be applied to a rusty surface.

1. Preparation:

- Remove any loose, flaky rust with a wire brush
- Make sure the surface is completely dry
- **BLACK-MAX™** is a ready to use product, **DO NOT DILUTE**
- Stir or shake the **BLACK-MAX™** container to assure product is blended well
- Always follow label instructions
- Use rubber gloves and safety goggles

2. Application:

- Apply the **BLACK-MAX™** with a paintbrush or roller
- Let **BLACK-MAX™** dry for approximately 3 to 4 hours
- Always wait at least 24 hours before painting over **BLACK-MAX™**
- To completely eliminate rust bleed-through always apply **BLACK-MAX™** to a rusty surface before you paint
- Clean-up of **BLACK-MAX™** is simple, just use soap and warm water

3. Coverage:

- The coverage is approximately 250 sq ft per gallon

4. Areas of Application:

- Anywhere you have rust

CALL TOLL FREE TO REORDER

